United States Department of the Interior Heritage Conservation and Recreation Service

National Register of Historic Places Inventory—Nomination Form

A Section of the same of the s	و ميرود در و. د
For HCRS use only	
received	
date entered	
Between a second and the second	

Invento	ry-Nomina	ition Form	date o	entered
	s in <i>How to Complete</i> N —complete applicable		Beng Salakabalagis, was	The same of the sa
1. Nam				And the second of the second o
historic	Ray, A. Taylor H	louse		
				· · · · · · · · · · · · · · · · · · ·
and/or common	Taylor Ray House	e, ruggre nouse		
2. Loca	ation			
street & number	212 West Van Bur	ren Street		not for publication
city, town	Gallatin	vicinity of	congressional district #6	- Hon. E. Thomas Cole
state	Missouri cod	le 029 county	Daviess	code 061
3. Clas	sification			
Category district X building(s) structure site object	Ownership public pr'vate both Public Acquisition in process being considered	Status _X_ occupied unoccupied _X_ work in progress Accessible _X_ yes: restricted yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park X private residence religious scientific transportation other:
<u>4. Own</u>	er of Prope	rty	The state of the s	
name	Mr. and Mrs. Stewa	art Marolf	;	
street & number	212 West Van Burer	Street		
city, town	Gallatin	vicinity of	state Mi	ssouri 64640
5. Loca	ation of Leg	al Descripti	on	
courthouse, regis	stry of deeds, etc. Reco	order of Deeds, Day	iess County Courthous	e
street & number	Cour	rthouse Square		
city, town	Ga11	latin "	state M	lissouri 64640
6. Repr	esentation	in Existing	Surveys	
				No.
		cal Survey has this pr	operty been determined eleg	Jible?yes _x no
<u>date 1978</u>			federalstate	_X_ county local
depository for su	rvey records Daviess	County Courthouse		
city, town Ga	llatin		state M	lissouri 64640

United States Department of the Interior Heritage Conservation and Recreation Service

National Register of Historic Places Inventory—Nomination Form

For HCRS use only received

date entered

Continuation sheet

RAY, A. TAYLOR HOUSE Item number

Page 1

2. Missouri State Historical Survey 1979, 1980
Department of Natural Resources P.O. Box 176
Jefferson City, Missouri 65102

no state

7. Description

Condition —— excellent —— good	deteriorated ruins	Check one unalteredX_altered	Check oneX_ original s moved	site date	
X. fair	unexposed				

Describe the present and original (if known) physical appearance

The A. Taylor Ray House, 212 West Van Buren, Gallatin, Missouri is a two story exposed frame house with clapboard and imbricated surface treatment, painted white with dark green trim and constructed in the Queen Anne Revival style. This house, which features a full, unfinished attic and basement, sits on a foundation of coursed, roughcut native limestone and is capped by pyramid, gable, hip, shed and mansard roofs which are covered with green asphalt shingles. Measuring 38' from east to west by 67' from north to south, this substantial home is located on a double corner lot in a residential area of the small town of Gallatin, Missouri just two blocks southwest of the town's main business district. Notable exterior design features include the octagonal tower to the northwest, the spindle, treillage, pendant and bentwood ornarent of the encircling veranda to the northeast and the second floor perches to the north and east and the many examples of applied jig-sawn floral motives in gables and other areas. Heavy incised brackets on the north and west sides and cornice level moldings enriched with anthemion and acanthus motives on the east and west sides complete the exterior enrichment. Inside, this house features curved window glass in its curving western bay, many elaborately carved mahogany, oak and walnut chimney pieces of classical inspiration with fancifully decorated cast iron grates, and double sliding oak doors dividing the main first floor areas. Other features include the carved oak central staircase enriched with spindles, decorative newels and surmounted by a spindled treillage on the second floor and the many substantial carved entryways with transoms.

Alterations include the remodeling of the kitchen and baths in the middle of this century. In addition, evidence within the construction suggests the existence of several minor interior alterations, such as the partition of the large bathroom on the second floor to create a sewing room and the opening of part of a wall for a doorway into the latter. The most notable change to the house has been the loss of the large south porch in a recent storm (see photo 5). Scars of this feature remain on the south side and the turned posts of its frame are kept in the basement.

See Continuation Sheet for a discussion of the condition of this building.

Continuation sheet

United States Department of the Interior Heritage Conservation and Recreation Service

National Register of Historic Places Inventory—Nomination Form

RAY, A. TAYLOR HOUSE

Item number

7

date entered

For HCRS use only

received

Page

The condition of the A. Taylor Ray House is only fair and bears some explanation. The house has many problems which are evident even during a preliminary inspection. For example, a look at the foundation reveals many significant cracks, some as wide as 3/4" - 1", with evidence of frequent patching on all interior basement bearing walls. Since the house suffers considerable subsidence to the north, both this movement and the cracks are probably results of some unknown forces below. The owners plan to use props below the first floor beams and joists in an effort to stem this subsidence and stabilize the house in its present position. Before they take this step suggestions were made that they monitor all major cracks with simple tell-tales to ascertain the amount and direction of movement of any which are still active and that they attempt to learn the reason for the subsidence and, if it is still occurring, to remedy it if Sometimes movement such as this is related to changes in ground water levels or soil configurations, or to the cave-in of hollow subterranean features, among other reasons. A consideration of the terrain, and a check of city water, sewer and road records could yield some information in this regard. The basement of this house was very damp with rising damp occurring to the south caused by cement wainscotting which is preventing evaporation around staircase up to the south exit. An examination of the exterior of the house quickly revealed at least part of the reason for basement dampness. Though the gutters were not examined from above, leaks were evidenced by watermarks and all downspouts discharge either directly onto the foundation or onto shallow splash plates without provision for drainage away from the house. Many of the downspouts are directly over large cracks in the foundation which allow the water to enter the basement. This water may even be additing to the subsidence through erosion of nearby sections of foundation and ground areas directly below downspouts.

In addition to the problems of faulty drainage and movement, a cursory inspection of the exterior of the house reveals that a major percentage of the woodwork of the porches and trim is riddled with rot and possibly insect infestation. The owners plan to replace it all with replicas. Finally, the owners have recently installed foam insulation to all exterior wall cavities. This action was taken without the addition of any vapor barrier, such as all interior coating of two layers of oil based paint. Nearly all the interior walls are papered rather than painted. Consequently, future problems caused by moisture condensation within the frame wall may result.

Footnotes

1. Preservation Brief No. 3 - Conserving Energy in Historic Buildings (Washington, D.C.: Technical Preservation Services Division, Heritage Conservation and Recreation Service, 1978), pp. 6-7.

8. Significance

Period prehistoric 1400–1499 1500–1599 1700–1799X 1800–1899 1900–	Areas of Significance—C archeology-prehistoric archeology-historic agricultureX architecture art commerce communications	community planning conservation economics education engineering exploration/settlement	politics/government	science sculpture X social/ humanitarian theater
Specific dates	1897	Builder/Architect	George Tuggle	

Statement of Significance (in one paragraph)

The A. Taylor Ray House is significant as the finest example of the free classic mode of the Queen Anne Revival in the town of Gallatin, Missouri. Moreover, it holds additional significance as the former home of the Ray and Tuggle families, both prominent in local and state affairs and government.

The free classic mode has been designated by Marcus Whiffen as the second phase of the Queen Anne Revival style, succeeding the Shavian Memorial phase of this style. Because the Shingle Style, a progressive movement which developed from the Queen Anne Revival, attracted many trained architects who might have been drawn to the Queen Anne Revival in the late nineteenth century, the free classic mode became an often unorthodox, often exhuberant development of less philosophically disciplined designers and builders. In the A. Taylor Ray House this exhuberance is seen in several details. The most notable of these are the anthemion relief on the cavetto molding above the curving bay on the west, the acanthus molding relief on the cavetto molding above the tripartite bay to the east, the carved sunburst in the gable of the primary facade, the distinctive woodwork of the encircling veranda and the rich interior carving and iron work (see photos).

The house was constructed by Mr. and Mrs. A. Taylor Ray, prominent members of the First Baptist Church of Gallatin, with a family member, George Tuggle, acting as architect. The Rays were both teachers and are noted for their generous financial gifts to their church and to William Jewell College, near Kansas City, Missouri. In addition, their gifts to benefit the children of the poor of Gallatin are well remembered. After the Rays passed away, Helen Weiser Tuggle, a niece of the Ray family, and her husband, Floyd Tuggle, lived in this house until 1950. Tuggle was a farmer who was instrumental in the organization of the Daviess County Extension Program and the Daviess County Soil and Drainage Districts. In addition, he served as president and chairman of the board of the First National Bank of Gallatin, a representative in the Missouri State Legislature for four terms, as a member of the local school board for twelve years and as a Rotarian for over thirty years.²

Footnotes

- 1. Marcus Whiffen, American Architecture Since 1780: A Guide to the Styles (Cambridge: M.I.T. Press, 1969), 118-119.
- 2. <u>History of Daviess and Gentry Counties, Missouri</u> (St. Louis: Historical Publishing Co., 1922), pp. 394-395 and Mrs. Stewart Marolf, interview with Jane Ann Tuggle Paul, October 1979.

9. Major l	Bibliographica	al Reference	es
	aviess and Gentry Coun	ties, Missouri. St	. Louis: Historical Publishing Co
3. Whiffen, Mar	Stewart. Personal int cus. American Architec M.I.T. Press, 1969.	erview with Jane Ar ture Since 1780: <i>P</i>	nn Tuggle Paul, October, 1979. A Guide to the Styles.
	raphical Data		
	property <u>approximately</u> l allatin	/2_acre	Quadrangle scale 1:62,500
A 1 5 4 1 7 6 Zone Easting	Northing	Zone Eas	sting Northing
ferhal boundary do	scription and justification		
In the county of	f Daviess and State of and four south in the	Missouri to wit: city of Gallatin.	all of lots three and four in
ist all states and c	ounties for properties over	rlapping state or count	y boundaries
tate	code	county	code
tate	code	county	code
11. Form	Prepared By		v-
ame/title /]. Noel]	e Soren, Architectural	Historian	,
	rtment of Natural Resou		October 24, 1980
treet & number P.O.	Box 176	: telepho	23.4 753 4000
ity or town Jeffe	erson City	state	Missouri 65102
	Historic Pres		ficer Certification
	nce of this property within the		
65), I hereby nominate		the National Register and	reservation Act of 1966 (Public Law 89– certify that it has been evaluated and Recreation Service.
tate Historic Preserva	tion Officer signature	i gned	
ile		, -	date 16 Feb 82
For HCRS use only I hereby certify th	nat this property is included in	the National Register	date
Keeper of the Nationa	al Register	· · · · · · · · · · · · · · · · · · ·	
Attest:			date
Chief of Registration			. 1

United States Department of the Interior Heritage Conservation and Recreation Service

National Register of Historic Places Inventory—Nomination Form

RAY, A. TAYLOR HOUSE

Item number

11

For HCRS use only received

date entered

Page


Continuation sheet

Mr. and Mrs. Stewart Marolf 212 West Van Buren Gallatin, Missouri 64640

816:663-3691

BUREAU OF GEOLOGY AND MINES H.A.BUEHLER, DIRECTOR AND STATE GEOLOGIST TOPOGRAPHY STATE OF MISSOURI A. TAYLOR RAY HOUSE 212 West Van Buren, Gallatin, Daviess County, MO. Quadrangle (1922-latest available) UTM REFERENCE: 15/417616/4418373 LATITUDE: 39 54 48.00 LONGITUDE: 93 57 50.00 DEPARTMENT OF THE INTERIOR
ALBERT B. FALL, SECRETARY
U.S. GEOLOGICAL SURVEY
GEORGE OTTS SMITH, DRECTOR
64'00 R.28 W. PARKED W. 151 Scale: 1:62500 "Gallatin" U.S.G.S. T. 60 N.

NOT TO SCALE



RAY, A. TAYLOR HOUSE

COUNTY:

LOCATION:

OWNER: ADDRESS:

212 West Van Buren St., Gallatin, Mo.

Daviess

Mr. & Mrs. Stewart Marolf 212 West Van Buren Street Gallatin, Mo. 64640

October 24, 1980

DATE APPROVED BY A.C.:

February 23, 1982

March 10, 1982

April 12, 1982

DATE PLACED ON NATIONAL REGISTER:

DATE OF REC. IN D.C.:

DATE SENT TO D.C.:


DATE CERTIFICATE AWARDED (AND PRESENTOR):

DATE FILE REVIEWED:

RAY, A. TAYLOR HOUSE
212 West Van Buren, Gallatin, Daviess County,
WO.
Photographer: Stewart Marolf
Winter, 1979
Neg. Loc.: 212 West Van Buren, Gallatin, MO.
64640
View to southeast.



RAY, A. TAYLOR HOUSE
212 West Van Buren, Gallatin, Daviess County,
MO.
Photographer: Stewart Marolf
Winter, 1979
Neg. Loc.: 212 West Van Buren, Gallatin, MO.
64640
Primary facade, view to south.



RAY, A. TAYLOR HOUSE #3 of 10 212 West Van Buren, Galla tin, Daviess County, MO.

Photographer: Stewart Marolf
Winter, 1979
Neg. Loc.: 212 West Van Buren, Gallatin, MO.
64640
Primary facade, detail, northwest tower.



RAY, A. TAYLOR HOUSE #\lpha of 10
212 West Van Buren, Gallatin, Daviess County,
MO.


Photographer: Stewart Marolf
Winter, 1979
Neg. Loc.: 212 West Van Buren, Gallatin, MO. 64640

View to west of east side.



RAY, A. TAYLOR HOUSE #5 of 10 212 West Van Buren, Gallatin, Daviess County, MO.


Photographer: Stewart Marolf
Winter, 1979
Neg. Loc.: 212 West Van Buren, Gallatin, MO. 64640
View to northwest of southeast corner.



RAY, A. TAYLOR HOUSE #6 of 10 212 West Van Buren, Gallatin, Daviess County, MO.

Photographer: Stewart Marolf
Winter, 1979
Neg. Loc.: 212 West Van Buren, Gallatin, Mo. 64640

View to east of west facade.



RAY, A. TAYLOR HOUSE

212 West Van Buren, Gallatin, Daviess County,
MO.
Photographer: Stewart Marolf
Winter, 1979

Neg. Loc.: 212 West Van Buren, Gallatin, MO.
64640

West side, second floor level, detail of cavetto molding with anthemion design.




RAY, A. TAYLOR HOUSE #8 of 10 212 West Van Buren, Gallatin, Daviess County, MO.

Photographer: Stewart Marolf Winter, 1979

Neg. Loc.: 212 West Van Buren, Gallatin, MO. 64640

Interior, first floor, sitting room, east wall, chimney piece.




RAY, A. TAYLOR HOUSE #9 of 10 212 West Van Buren, Gallatin, Daviess County, MO.

Photographer: Stewart Marolf Winter, 1979

Neg. Loc.: 212 West Van Buren, Gallatin, MO.

64640

Interior, first floor, sitting room, east wall, chimney piece, detail of griffin,



RAY, A. TAYLOR HOUSE
212 West Van Buren, Gallatin, Daviess County,
MO.
Photographer: Stewart Marolf
Winter, 1979
Neg. Loc.: 212 West Van Buren, Gallatin, MO.
64,64,0

Interior, first floor, dining room, ornamental iron grate at fireplace.

